

2009 Fire Alarm Log

Incident Date	Building	Incident Description
1/5/2009 22:49	Founders Residence Hall	Alarm Fire Trouble Simplex
1/9/2009 19:55	Thompson Gymnasium	Fire Alarm EMS System
1/11/2009 22:12	Myer Residence Hall	Alarm Fire Simplex System
1/16/2009 21:15	Ober Residence Hall	Alarm Fire Simplex System
1/21/2009 12:06	Ober Residence Hall	Alarm Fire Simplex
1/23/2009 18:43	Ober Residence Hall	Alarm Fire Simplex System
1/24/2009 20:40	Ober Residence Hall	Alarm Fire Trouble Simplex
1/25/2009 12:40	Brossman Commons	Alarm Fire Simplex System
1/26/2009 8:44	Myer Residence Hall	Alarm Fire Simplex System
1/26/2009 18:43	Brossman Commons	Alarm Fire Simplex
1/28/2009 18:25	Myer Residence Hall	Alarm Simplex-Fire
1/29/2009 1:25	Brinser Residence Hall	Alarm Fire-Simplex
2/2/2009 16:07	Wenger Center	Alarm Fire EMS System
2/4/2009 21:55	Myer Residence Hall	Alarm Fire, Simplex System
2/5/2009 4:31	Musser Hall	Alarm-Fire, Trouble EMS System
2/6/2009 9:36	Wenger Center	Alarm Fire Trouble EMS System
2/6/2009 13:21	Wenger Center	Alarm Fire Trouble EMS System
2/7/2009 6:35	Wenger Center	Alarm Fire Trouble EMS System
2/8/2009 0:34	Rose Garden 320 East Orange Street	Alarm Fire Simplex System
2/8/2009 0:45	Vera Hackman Apartments	Alarm Fire Tampering
2/10/2009 0:00	Myer Residence Hall	Alarm-Fire Simplex System
2/13/2009 20:47	Wenger Center	Alarm Fire Trouble EMS
2/14/2009 12:50	Schreiber Quadrangle	Alarm Fire Simplex System
2/19/2009 12:01	Myer Residence Hall	Alarm Fire Simplex System
2/22/2009 14:07	Steinman Hall	Alarm Fire EMS Computer
2/22/2009 22:26	Schlosser Residence Hall	Alarm Fire Simplex System
2/27/2009 18:00	Founders Residence Hall	Alarm Fire Trouble Simplex
3/1/2009 21:56	Ober Residence Hall	Alarm Fire Simplex System
3/6/2009 9:34	Ober Residence Hall	Alarm Fire Simplex System
3/7/2009 10:21	Myer Administration	Alarm Fire Simplex System
3/15/2009 19:42	Founders Residence Hall	Alarm Fire Simplex System
3/22/2009 16:21	Brinser Residence Hall	Alarm Fire Simplex System
3/22/2009 22:28	Ober Residence Hall	Alarm Fire Simplex System
3/26/2009 0:56	Ober Residence Hall	Alarm Fire Trouble-Simplex System
4/2/2009 17:15	Vera Hackman Apartments	Alarm Fire-Simplex
4/2/2009 18:10	Vera Hackman Apartments	Alarm Fire Simplex

2009 Fire Alarm Log

Incident Details

Smoke detector activated.

Pull station activated at pool by 3 year old from Aquatics Club family. Reset old & new systems and pull station.

Myer smoke detector activated dud to burnt popcorn.

Burnt popcorn activated detector. System reset.

Occupants of Ober 204 burnt cookies. Smoke detector activated. Reset panel.

Ober 1st floor smoke detector activated. Normal. No fire. System reset.

Alarm due to dirty smoke detector.

Marketplace kitchen detector activated. Found no cause for alarm. Reset.

Myer 2nd floor 254 smoke detector/fire alarm activated by hair dryer. Reset. Contacted A/C on call.

Smell of smoke from burnt food in vicinity of grill. There was a flame up from grill prior to alarm. Unable to reset. Alarm disabled.

Shower steam activated alarm.

Popcorn smoke activated fire alarm. Reset.

Wenger Center fire trouble.

Alarm came over Simplex and went to normal. Student called to say it was activated by shower. CSO's 8 & 9 dispatched to check. Reset panel.

Musser Hall unit 5 showed a low temp. Since temp outside is below 40 degrees, contacted MTOC to check it out.

Wenger Center fire trouble. Unknown problem. Reset.

Wenger Center fire trouble. No fire or smoke detected. Silenced alarm. Contacted G. Dupler regarding fire panel.

Trouble alarm would not reset in Wenger.

Rose Garden fire alarm activated by smoke from cooking pancakes. Reset panel in basement.

Alarm activated. arrived on scene to find water discharging from sprinkler system and starting to flood basement. Did full check of building but found no fire, no sprinkler head activated. No one in building.

Burnt popcorn activated smoke detector in Myer 3rd floor lounge. Reset alarm.

Wenger Center fire trouble. No cause for trouble found. Unable to reset system.

Occupant of Quad E1 called and said burnt food set off smoke detector. Reset panel.

Myer second floor room 223 smoke detector activated by shower. Reset.

Student working w/ clay powder and exhaust fan activated smoke detector in Steinman Hall. System reset.

Schlosser ground floor resident bedroom smoke detector activated by burnt food. Opened all windows and reset system.

Founders Hall Dwing smoke detector activated.

Detector activated by cooking. System reset.

Alarm activated in Ober basement. Dust from varnish set off alarm. Alarm silenced and reset.

Dining crew setting up for a birthday party. Alarm is activated when balloons are involved. Alarm silenced and reset.

Stdudents reported that detectors kept beeping. Smoke detector head missing. CSO Roman put detector head back on and heard nothing.

Alarm activated due to burnt bacon. Reset panel.

Alarm caused by cooking in microwave. Vented room and reset alarm.

Alarm activated due to burnt popcorn. Cleared room of smoke and reset alarm.

Cooking smoke activated smoke detector. Reset system.

Fire alarm in Hackman North 155 activated by cooking. System reset.

2009 Fire Alarm Log

Incident Date	Building	Incident Description
4/5/2009 12:42	Myer Residence Hall	Alarm Fire Simplex System
4/5/2009 13:46	Myer Residence Hall	Alarm Fire Simplex System
4/13/2009 19:12	Vera Hackman Apartments	Alarm Fire Simplex System
4/18/2009 19:33	Roadways and Streets	Alarm Fire, Trouble, Simplex System
4/19/2009 1:57	Brossman Commons	Alarm- Fire Simplex System
4/23/2009 11:59	Vera Hackman Apartments	Alarm Fire Simplex System
4/23/2009 20:24	Ober Residence Hall	Alarm Fire Simplex System
4/24/2009 2:47	Royer Residence Hall	Alarm Fire Simplex
4/26/2009 22:01	Schreiber Quadrangle	Fire Trouble Simplex System
4/28/2009 18:28	Brossman Commons	Alarm Fire Simplex System
5/2/2009 16:20		Alarm Fire Simplex System
5/4/2009 20:11	Brinser Residence Hall	Alarm Fire Simplex
5/5/2009 19:13	Myer Administration	Alarm Fire, Simplex System
5/9/2009 23:49	Ober Residence Hall	Fire Code Violation/Unsafe condition outside
5/11/2009 21:13	Brinser Residence Hall	Alarm Fire Simplex System
5/12/2009 11:18	Royer Residence Hall	Alarm Fire Simplex System
5/12/2009 19:36	Nicarry Hall	Alarm Fire Trouble Simplex System
5/13/2009 22:27	Myer Residence Hall	Alarm Fire Simplex System
5/17/2009 0:16	Schreiber Quadrangle	Fire Department Requested
5/25/2009 7:58	Brinser Residence Hall	Alarm Fire, Simplex System
5/26/2009 17:53	Vera Hackman Apartments	Alarm Fire Simplex System
5/28/2009 11:08	Brossman Commons	Alarm Fire Simplex System
5/28/2009 20:41	Vera Hackman Apartments	Alarm Fire Simplex System
6/10/2009 10:31	Schlosser Residence Hall	Alarm Fire Simplex System
6/11/2009 19:34	Royer Residence Hall	Alarm Fire Simplex System
6/17/2009 14:18	Zug Memorial Hall	Alarm Fire Trouble
6/18/2009 13:16	Myer Administration	Alarm Fire Trouble Simplex System
6/26/2009 11:29	Musser Hall	Alarm Fire Simplex System
6/28/2009 11:52	Vera Hackman Apartments	Alarm Fire Simplex System
7/3/2009 1:14	Founders Residence Hall	Alarm Fire Simplex System
7/3/2009 13:37	Founders Residence Hall	Alarm Fire Simplex System
7/14/2009 10:30	Myer Administration	Alarm Fire Simplex System
7/16/2009 10:37	Founders Residence Hall	Alarm Fire Simplex System
7/17/2009 13:33	320 Plum Street	Alarm Fire Simplex System
7/17/2009 20:26	Founders Residence Hall	Alarm Fire Simplex System
7/20/2009 7:40	Brossman Commons	Alarm Fire Simplex System

2009 Fire Alarm Log

Incident Details

CSO Miller responded to Myer 223 for fire alarm activated by steam. Reset system.

CSO Miller arrived at Myer to find alarm caused by steam. Reset system and spoke to students about ventilating room while showering.

Detector activated by cooking. Reset system.

Hair dryers set off smoke alarm in Quad E2.

Unknown person pulled fire pull station at handicapped entrance next to Jay's Nest. Pull station and panel reset.

CSOs Boyer and Williams responded to VHA N for fire alarm. No cause apparent. Silenced alarm and reset. When leaving, Randy from ES said he had bumped the CO2 detector accidentally.

Burnt popcorn activated alarm. Smoke cleared and system was reset.

Alarm activated by steaming iron. Reset panel.

Smoke detectors activated Quad E2. CSO Patrick checked. Everything was OK. All smoke detectors fine.

Simplex showed CC basement mechanical room heat detector. CSO Roman found nothing wrong. Reset system.

Water had boiled over in Room 201. Alarms audible. Silenced and reset alarm system.

Smoke detector activated in Brinser by burnt food.

Balloons in dining hall were set free and set off fire alarms.

Extinguished small fire in cigarette container located rear porch of Ober.

Alarm activated by steam from shower. Reset system.

Smoke detector activated by spray painting of ceiling tiles. Panel reset.

Pull station in Nicarry was pulled by a young child. Area checked by officers. Pull station was reset.

Smoke detector activated by burnt popcorn. System reset.

RP observed large fire in grassy area of Quads with flames 8-10 feet high. Requested fire department.

Alarm pulled by small child in lobby of Brinser. Reset alarm and reset panel.

Cooking set off alarm in VHAN 157. Alarm was reset.

Fire alarm activated by cleaners working on ductwork.

Smoke detector activated by burnt food. System reset.

Smoke from AC/heater unit activated smoke detector. Plant Ops notified.

CO detector activated by emergency generator running due to power outage. Disabled zone until after CO level returned to normal and detector was silent.

EMS system reading fire trouble in Zub. Appears student workers disconnected fire alarm and tripped it.

Myer first floor Susquehanna Room detector activated. CSO Williams found nothing wrong. Panel reset.

Smoke detector in Musser 1st floor room 106 activated by contractors doing work on ceiling. System turned off until work is done. System reset.

Responded to Hackman North 253 for alarm activated by burnt food.

Heat detector activated fire alarm. No cause for alarm found. System reset.

Founders first floor heat detector activated. No cause for alarm. Detector disabled until repair/replacement can be made.

Fire alarm activated by Plant Ops working on ballests.

Fire alarm sounding in Founders B203. Nothing found. Reset panel.

Smoke detector on Plum Street activated. Plant Ops sanding ceiling and walls activated detector.

Dectector activated possibly by dust. Reset system.

Plant Ops working on duct detector set off alarm. Panel reset after everything confirmed OK.

2009 Fire Alarm Log

Incident Date	Building	Incident Description
7/20/2009 8:49	Founders Residence Hall	Alarm Fire Trouble Simplex System
7/20/2009 11:06	Royer Residence Hall	Alarm Fire Simplex System
7/22/2009 14:05	Royer Residence Hall	Alarm Fire Simplex System
7/30/2009 17:51	Myer Residence Hall	Alarm Fire Simplex System
7/30/2009 19:57	Baughner Student Center	Alarm Fire Simplex System
7/31/2009 11:07	Myer Administration	Alarm Fire Simplex System
8/3/2009 18:25	Ober Residence Hall	Alarm Fire Simplex System
8/8/2009 9:22	Royer Residence Hall	Alarm Fire Simplex System
8/19/2009 9:38	White House 540 S Mt Joy St	Alarm Fire Simplex System
8/19/2009 14:47	Founders Residence Hall	Alarm Fire Simplex System
8/20/2009 8:03	Zug Memorial Hall	Alarm Fire Reported by Person
8/21/2009 7:29	White House 540 S Mt Joy St	Alarm Fire Simplex System
8/21/2009 8:25	White House 540 S Mt Joy St	Alarm Fire Simplex System
8/23/2009 8:21	Founders Residence Hall	Alarm Fire Simplex System
8/25/2009 10:40	Myer Residence Hall	Alarm Fire Simplex System
8/26/2009 6:22	Founders Residence Hall	Alarm Fire Trouble Simplex System
8/30/2009 1:59	Founders Residence Hall	Alarm Fire Simplex System
8/31/2009 10:00	Schlosser Residence Hall	Alarm Fire Simplex System
8/31/2009 22:05	Baughner Student Center	Alarm Fire Simplex System
9/2/2009 0:37	Royer Residence Hall	Alarm Fire Simplex System
9/4/2009 15:14	Royer Residence Hall	Alarm Fire Simplex System
9/6/2009 8:33	Royer Residence Hall	Alarm Fire Simplex System
9/7/2009 1:34	Vera Hackman Apartments	Alarm Fire Simplex System
9/7/2009 2:24	Rose Garden 320 East Orange Street	Alarm Fire Simplex System
9/11/2009 20:47	Brossman Commons	Alarm Fire Simplex System
9/13/2009 4:28	Ober Residence Hall	Alarm Fire Simplex System
9/13/2009 15:21	Vera Hackman Apartments	Alarm Fire Simplex System
9/13/2009 20:42	Campus Security	Alarm Fire Trouble Simplex System
9/15/2009 17:31	Myer Residence Hall	Alarm Fire Simplex
9/15/2009 17:58	Myer Residence Hall	Alarm Fire Simplex System
9/17/2009 20:42	Cedar House 625 S Mt Joy St	Alarm Fire Trouble
9/18/2009 9:07	Myer Administration	Alarm Fire Simplex
9/19/2009 10:14	Royer Residence Hall	Alarm Fire Simplex System
9/23/2009 17:52	Founders Residence Hall	Alarm Fire Alarm Simplex
9/23/2009 20:23	Founders Residence Hall	Alarm Fire Simplex
9/24/2009 2:44	Vera Hackman Apartments	Alarm Fire Simplex System

2009 Fire Alarm Log

Incident Details

Contractors cutting brick set off smoke detector. Disabled detector and reset panel.

Contractors cutting metal with a saw set off CO2 detector. Disabled detector and reset panel.

Audio/visual device on wall wet from Plant Ops spraying door with water. Shorted out system. Dried out device and restarted system.

Myer 3rd floor smoke detector activated. System reset.

CC Basement mechanical room heat detector needed to be checked by MTOC for excessive heat.

Myer 1st floor Susquehanna beam detector activated. Fire monitor zone normal. CSO Smith disabled for Plant Ops work and also for wedding until Monday.

Ober 1st floor RA suite kitchen. Smoke detector activated by cooking. Alarm reset.

Fire alarm set off due to electrical shut down in Royer.

Simplex technician reported alarm going off in White House. Received no alarm in Security office. No cause found. Alarm reset.

High room temp reported in Founders mechanical room. May be due to generator.

Fire alarm did not come across board at Security. EMS is down. Reported by RP.

CO2 alarm activated. Found no cause. Reset system.

Alarm sounding in White House again. Detector head cleaned. No other cause found for alarm.

Alarm activated by shower in Founders Hall B wing.

Smoke detector activated in Myer 208. Maintenance had set off alarm. System reset.

Smoke detector activated in Founders C RD apartment. RD notified.

Smoke detector activated FH Cwing 1st floor. Activated for no apparent reason. System reset.

Smoke detector activated by occupant microwaving food. Panel reset.

Pull station at BSC info desk set off by Simplex Company.

Smoke detector activated by shower in Royer.

Detector activated by football thrown in hallway.

Smoke detector activated in Royer 322 from shower steam. Alarm reset.

Alarm activated in Hackman North. See also inc. 09-1210. MTOC contacted.

Alarm activated by burnt food. System reset.

Smoke detector activated by SWEET making popcorn directly under detector. Reset system and asked them not to use machine under detector again.

Ober basement Bwing restroom heat detector activated for no apparent reason. CSO Norrie disable detector after contacting Jack Longenecker.

Burnt cookies set off alarm in VHA 206. Reset panel.

Common trouble point node 9 earth ground.

Myer 1st floor office/kitchen smoke detector activated due to burnt food. Alarm reset and students permitted back into building.

Alarm in Myer 3rd floor activated by cooking. Alarm reset.

Cedar House smoke detector activated by steam from shower. System reset.

Contractors blowing insulation activated detector. Disabled system until they are done.

Smoke detector activated by shower steam. Cleared alarm.

Alarm activated by dirty smoke detector.

Pull station alarm in Founders D 1st floor living room. System reset.

Smoke detector activated in Hackman 357. No apparent cause for alarm.

2009 Fire Alarm Log

Incident Date	Building	Incident Description
9/25/2009 21:42	White House 540 S Mt Joy St	Alarm Fire Simplex System
9/27/2009 22:21	Vera Hackman Apartments	Alarm Fire Simplex System
9/30/2009 10:42	318 Plum Street	Alarm Fire Simplex System
9/30/2009 22:29	Schlosser Residence Hall	Alarm Fire Simplex
9/30/2009 22:48	Myer Residence Hall	Alarm Fire Simplex
9/30/2009 23:26	Myer Residence Hall	Alarm Fire Simplex System
10/1/2009 20:33	Esbenshade Hall	Alarm Fire Simplex
10/3/2009 21:05	Founders Residence Hall	Alarm Fire Simplex System
10/5/2009 11:53	Schreiber Quadrangle	Alarm Fire Simplex System
10/13/2009 17:30	Royer Residence Hall	Alarm Fire Simplex System
10/14/2009 16:17	Vera Hackman Apartments	Alarm Fire Simplex System
10/18/2009 19:04	Founders Residence Hall	Alarm Fire Trouble
10/18/2009 20:33	Campus Security	Alarm Fire EMS Computer
10/19/2009 7:21	Royer Residence Hall	Alarm Fire Simplex System
10/19/2009 8:56	Royer Residence Hall	Alarm Fire Simplex System
10/20/2009 13:21	Maple House 435 College Aveune	Alarm Fire Simplex System
10/21/2009 2:20	Vera Hackman Apartments	Alarm Fire Simplex System
10/21/2009 21:16	Vera Hackman Apartments	Alarm Fire, Simplex System
10/24/2009 14:19	Baughner Student Center	Alarm Fire, Simplex System
10/24/2009 18:34	Myer Residence Hall	Alarm Fire-Simplex System
10/25/2009 4:22	Hoover Business Building	Alarm Fire Trouble Simplex
10/27/2009 20:16	Vera Hackman Apartments	Alarm Fire Simplex System
10/31/2009 11:03	Founders Residence Hall	Alarm Fire Simplex System
11/3/2009 22:42	Ober Residence Hall	Alarm Fire Simplex System
11/5/2009 16:02	Vera Hackman Apartments	Alarm Fire Simplex System
11/6/2009 23:04	Myer Residence Hall	Alarm Fire Trouble EMS Computer
11/7/2009 12:24	Founders Residence Hall	Alarm Fire Simplex System
11/9/2009 18:06	Schreiber Quadrangle	Alarm Fire Simplex
11/9/2009 22:13	Founders Residence Hall	Alarm Fire Simplex System
11/10/2009 10:27	Schlosser Residence Hall	Alarm Fire Simplex System
11/16/2009 11:21	Royer Residence Hall	Alarm Fire Simplex System
11/17/2009 10:25	Myer Residence Hall	Alarm Fire Simplex System
11/20/2009 23:47	Royer Residence Hall	Alarm Fire Simplex System
11/21/2009 23:01	Vera Hackman Apartments	Alarm Fire Simplex System
11/22/2009 0:28	Cedar House 625 S Mt Joy St	Alarm Fire Simplex System
11/23/2009 6:12	Founders Residence Hall	Alarm Fire Trouble Simplex

2009 Fire Alarm Log

Incident Details

Alarm activated by carbon monoxide detector being hit in basement by one of the residents. Reset system.

Smoke detector activated for no reason. Detector disconnected and was attempted to be reset. Would not reset. Removed and replaced with a new detector.

Smoke detector activated by burned food.

Alarm activated but no cause found. System reset.

Alarm activated from residents using hair dryer. System reset.

Smoke detector activated by burnt food.

Unattended child pulled pull station in Gible. System reset.

Detector activated by shower heat.

Smoke detector activated in Quad D1 from cooking bacon. Alarm reset.

Smoke detector activated due to popcorn. Alarm reset.

Smoke detector activated due to burned food.

Report of power outage and alarm going off in High Library.

High Library smoke detector activated.

Royer 2nd floor smoke detector activated by shower steam. Panel reset.

Royer 2nd floor smoke detector activated by shower steam. Alarm reset.

Alarm activated by insulation being blown in.

Received smoke alarm message for Hackman 357. According to resident, alarm never sounded in their apartment.

Fire alarm activated by burnt food. Verified cause, vented building and reset alarm.

Smoke detector activated due to popcorn machine. Alarm reset.

Smoke detector activated by cooking fire in 1st floor kitchenette.

Hoover supply fan has failed. MTOC contacted.

Alarm activated in HN 3rd floor 357. Resident of room did not know an alarm was going off. Student stated they have had phantom alarms several times in the last few weeks. No problem found.

Heavy steam from shower activated alarm in Founders Bwing 3rd floor. Silenced alarm and reset.

Burned food activated smoke detector in Ober. Alarm reset.

Burnt food activated smoke detector in VHAN 157. Panel reset.

Myer residence boiler alarm activated. MTOC contacted.

Smoke detector activated in Founders Bwing. Smells like candle had been burning but found that it was burnt hair from someone using a hair straightener. Panel reset.

Smoke detector activated in Quads by steam from shower.

Smoke detector activated in Founders.

Contractors set off smoke detector with insulation dust.

Alarm activated by candle. Student informed that candles are not permitted.

Burnt popcorn activated fire alarm in Myer 3rd floor. Everything is OK. Alarm reset.

Alarm activated in Royer by burnt food. Had room vented and reset alarm.

Alarm activated by burnt food. Room was vented and alarm reset.

Alarm activated at Cedar House for no reason. Left note for residents and contacted Simplex.

Dirty smoke detector activated alarm in Founders D-wing.

2009 Fire Alarm Log

Incident Date	Building	Incident Description
11/24/2009 1:26	Cedar House 625 S Mt Joy St	Alarm Fire Simplex
11/24/2009 15:26	Zug Memorial Hall	Alarm Fire EMS Computer
11/24/2009 19:56	Maple House 435 College Aveune	Alarm Fire Simplex System
11/29/2009 22:47	Ober Residence Hall	Alarm Fire Simplex System
12/1/2009 18:02	Vera Hackman Apartments	Alarm Fire Simplex System
12/2/2009 18:23	Ober Residence Hall	Alarm Fire Simplex
12/3/2009 8:20	Cedar House 625 S Mt Joy St	Alarm Fire Simplex System
12/3/2009 22:07	Vera Hackman Apartments	Alarm Fire Simplex
12/4/2009 13:44	Schlosser Residence Hall	Alarm Fire Alarm Simplex
12/4/2009 22:52	Ober Residence Hall	Alarm Fire Simplex System/Alarm Fire Tampering
12/5/2009 2:28	Ober Residence Hall	Alarm Fire Simplex/ Alarm Fire Tampering
12/5/2009 11:32	Thompson Gymnasium	Alarm Fire EMS Computer
12/6/2009 1:08	Maple House 435 College Aveune	Alarm Fire Simplex System
12/9/2009 21:23	Myer Residence Hall	Alarm Fire Simplex System
12/13/2009 18:56	Vera Hackman Apartments	Alarm Fire Simplex System
12/13/2009 20:27	Schlosser Residence Hall	Alarm Fire Trouble Simplex System
12/15/2009 19:23	Cedar House 625 S Mt Joy St	Alarm Fire Simplex System
12/17/2009 15:45	Schlosser Residence Hall	Alarm Fire Simplex
12/18/2009 15:03	Myer Administration	Alarm Fire Simplex System

2009 Fire Alarm Log

Incident Details

Student called to say steam from shower activated alarm.

Burnt popcorn activated alarm in Zug Business Office. Panel reset.

Burnt food activated alarm in Maple House. Doors and windows opened to vent and alarm reset.

Alarm activated by burnt popcorn. Dispatch reset alarm.

Burnt food activated fire alarm. Cleared area of smoke and reset alarm.

Alarm activated in Ober 1st floor RA suite kitchen. Found no know cause. Alarm reset.

Steam from shower set off alarm. Panel reset.

Alarm activated in Hackman S 102. Found no cause for alarm. System reset.

Burnt popcorn activated alarm in Schlosser. Panel reset.

Pull station in Ober activated. Box reset and dispatch reset system.

Pull box station on lobby level of Ober and RA office activated. Box and building system reset.

EMS reads gym alarm activated. Panel reset.

Student unplugged CO2 detector by mistake and triggered alarm. Alarm reset and detector connected.

Burnt popcorn activated alarm. System reset.

Alarm activated in Hackman 357. CSO Smith found nothing. System reset.

Smoke detector activated 2nd floor Schlosser. Dirty detector.

Steam in shower set off fire alarm. System reset.

Burnt popcorn activated alarm in Schlosser. Panel reset.

Carpenters working on ceiling in front of beam detector set off fire alarm. Reset panel.